

# Changeover COMPASS Trigger 2018

Benjamin Moritz Veit

9. Januar 2018

# Changeover 2018

Included hodoscopes:

HG01, HG02, HO03, HO04, HM04Y, HM05Y, HI05

- Gluing two HO03 slabs (excepted delivery 05.03.2018)
- Installing DY HO03 and HO04 slabs
- Moving middle horizontal hodoscopes
- Survey of HG01 and fixing position and stability
- Setup of di-muon trigger
- Calibration of calorimeter trigger
- Recheck of working points
- Repair of HG01 channels
- Further improvement of HG01 magnetic shielding
- Plans for efficiency run cycle ?